



РАЗМЕРЫ МА | МАНОМЕТРЫ И ВАКУУММЕТРЫ


LM - Радиальное присоединение (вниз)




CM - Осевое присоединение (по центру сзади)



PM - Панельного монтажа



FM - Панельного монтажа с передним фланцем



Маркировка	A	B	S	D	D1	M	L	C	F	G	SW
MA-40-LM-...-G18	25	-	-	40	-	57.5	57.5	-	-	G1/8"	11
MA-50-LM-...-G14	28	-	-	49	-	68.5	68.5	-	-	G1/4"	14
MA-40-CM-...-G18	25	-	-	40	-	40	40	-	-	G1/8"	11
MA-50-CM-...-G14	27.5	-	-	49	-	48	48	-	-	G1/4"	14
MA-40-PM-...-G18	25.25	5.25	-	44.2	40.5	40.5	40.5	-	-	G1/8"	11
MA-50-PM-...-G14	27	4.6	-	57.5	51.5	48.5	48.5	-	-	G1/4"	14
MA-40-FM-...-G18	25	-	3	40	-	40	40	48.6	55	G1/8"	11
MA-50-FM-...-G14	27.5	-	3	49	-	48	48	60.5	65	G1/4"	14